



Paper #23

## Will New Metal Heads Restore the Mechanical Integrity of Corroded Trunnions at Revision THR?

Jerry W. Alexander, BS, Jonathan Gold, BS, Stephen J. Incavo, MD, Philip C. Noble, PhD, Rikin Patel, MS, **Aditya M. Derasari, MD**, Mohamed S. Gobba, MD, Sang Woo Kim, MD

**Introduction:** Mechanically-assisted corrosion at the head-neck junction can be seen at revision THA. Many surgeons exchange the femoral head to avoid the morbidity of revising a well-functioning femoral stem. Our study asks: 1. Will new metal heads on corroded tapers restore the mechanical integrity of the original junction? 2. Which variables affect the stability of the new interface created at revision THR?

**Methods:** Twenty-two tapers (CoCr, n=12; TiAlV, n=10) were obtained for use in this study from our retrieval collection. Ten stems were in pristine condition, while 12 stems were with corroded trunnions (Goldberg scale 4). Twenty-two new matching metal heads were obtained for use in the study. The following test states were performed using a MTS Machine: 1. Assembly, 2. Disassembly, 3. Assembly, 4. Toggling and 5. Disassembly. During loading, 3D motion of the head-trunnion junction was measured using a custom jig. Relative displacement of the head was continuously monitored using 6 high resolution displacement transducers with an accuracy of  $\pm 0.6\mu\text{m}$ .

**Results:** The average micromotion was greatest at initial loading and stabilized after approximately 50 loading cycles at an average of  $30.6\pm 3.2\mu\text{m}$ . For CoCr couples, interface motion dropped by 17% with a pristine head on a corroded stem compared to a new stem ( $25.7\pm 2.7\mu\text{m}$  (pristine stem), vs.  $30.1\pm 4.6\mu\text{m}$  (corroded stem),  $p=0.4023$ ). However, a new CoCr head on a corroded titanium stem led to a 73% increase in interface motion (Corroded:  $43.4\pm 9.8\mu\text{m}$ , Pristine:  $25.2\pm 7.0\mu\text{m}$ ,  $p=0.1661$ ). Resistance to head-neck disruption was 15% higher in TiAlV/CoCr couples compared to CoCr/CoCr (TiAlV:  $2558\pm 63\text{N}$ , CoCr:  $2226\pm 99\text{N}$ ,  $p=0.0111$ ) and was not affected by trunnion corrosion.

**Conclusion:** Trunnion corrosion does not disrupt the mechanical integrity of the junction when a CoCr head is replaced on a CoCr taper. We are less sure about TiAlV tapers as demonstrated by a trend towards increased micromotion at the head-neck junction.

---